



A. MAKARIAN COMMERCIAL-TECHNICAL

85-87 METHONIS str, PIRAEUS 18547, GREECE
Phone: +30 210 4615946, 4615272 FAX: +30 210 4627044
www.mmakarian.gr e mail: mmakarian@mmakarian.gr

DIESEL FUEL INJECTION SERVICE, SUPPLIER, MANUFACTURER

FUEL INJECTOR WHICH NEEDS REPAIR GRINDING - LAPPING



FUEL INJECTOR AFTER GRINDING & LAPPING



The fuel injectors with damaged surface or wear in the middle of the surface create the problems below:

1. The nozzle does not spray, even if it's new or slightly used.
2. Will cause a higher needle lift for the fuel injection nozzle, the higher needle lift is lowering the service life of the nozzle and sprays - delivery twice amount of the regular condition

At your disposal for any information.

Thanks & Kindest Regards,
A.Makarian Co
Merkouris Kouminos