

DRAEGER

XS Sensors for use with the following gas monitors: X-am 7000, X-am 5100

The HF/HCl, H₂O₂, and hydrazine are only used in the X-am 5100.

REPLACEMENT TOXIC AND OXYGEN SENSORS FOR PORTABLES - DrägerSensors provide superior value, with long term operation and fast, accurate readings. Our O₂, CO and H₂S sensors have warranties of up to 5 years. Dräger offers the broadest line of toxic gas sensors in the industry.

These electrochemical sensors are transducers for measuring the partial pressure of toxic gases or oxygen in ambient air.

XS-R DrägerSensor®			
Description	Measuring Range	Resolution	Part No. Replace.
Carbon Monoxide (CO)	0 - 2000 ppm	1 ppm	6810258
Hydrogen Sulfide (H ₂ S)	0 - 100 ppm	1 ppm	6810260
Oxygen (O ₂)	0 - 25% Vol	0.1% Vol.	6810262
XS DrägerSensor®			
Description	Measuring Range	Resolution	Part No. Replace.
Amines XS	0 - 100 PPM	1 ppm	6809545
Ammonia (NH ₃) XS	0 - 300 PPM	1 ppm	6809145
Carbon Dioxide (CO ₂) XS	0 - 0.05 Vol.	0.10% Vol.	6809175
Carbon Monoxide (CO) XS	0 - 2000 PPM	1 ppm	6809105
Carbon Monoxide (CO) XS HC	0 - 10000 ppm	5 ppm	6809120
Chlorine (Cl ₂) XS	0 - 20 ppm	0.1 ppm	6809165
Chlorine Dioxide (ClO ₂) XS	0 - 20 ppm	0.01 ppm	6811360
Hydrazine (N ₂ H ₄) XS	0 - 3 ppm	0.01 ppm	6809190 [§]
Hydride XS (Phosphine, Arsine, etc.)	0 - 20 ppm	0.1 ppm	6809135
Hydrogen (H ₂) XS	0 - 2000 ppm	1 ppm	6809185
Hydrogen (H ₂) XS HC	0 - 4 %Vol.	0.1 %Vol	6811365
Hydrogen Cyanide (HCN) XS	0 - 50 ppm	0.1 ppm	6809150
Hydrogen Fluoride/Hydrogen Chloride (HF/HCl) XS	0 - 30 ppm	0.1 ppm	6809140 [§]
Hydrogen Peroxide (H ₂ O ₂) XS	0 - 20 ppm	0.1 ppm	6809170 [§]
Hydrogen Sulfide (H ₂ S) XS	0 - 100 ppm	1 ppm	6809110
Hydrogen Sulfide (H ₂ S) XS HC	0 - 100 ppm	1 ppm	6809180
Hydrogen Sulfide (H ₂ S) XS-2 SR	0 - 100 ppm	1 ppm	6810575
Nitrogen Dioxide (NO ₂) XS	0 - 50 ppm	0.1 ppm	6809155
Nitric Oxide (NO) XS	0 - 200 ppm	1 ppm	6809125
Odorant XS	0 - 40 ppm	0.5 ppm	6809200
Organic Vapor (OV) XS	0 - 200 ppm	0.5 ppm	6809115
Organic Vapor-A (OV-A) XS	0 - 100 ppm	0.5 ppm	6809522
Oxygen (O ₂) XS	0 - 0.25 Vol.	0.10% Vol.	6809130
Oxygen (O ₂) XS-100	0 - 1 Vol.	0.50% Vol.	6809550
Phosgene (COCl ₂) XS	0 - 3 ppm	0.01 ppm	6808582
Phosphine (PH ₃) XS HC	0 - 1000 ppm	1 ppm	6809535
Sulfur Dioxide (SO ₂) XS	0 - 100 ppm	0.1 ppm	6809160
[§] This sensor can only be used with X-am 5100.			
XS-2 DrägerSensor®			
Description	Measuring Range	Resolution	Part No. Replace.
Carbon Monoxide (CO) XS-2	0 - 2000 ppm	1 ppm	6810365
Hydrogen Sulfide (H ₂ S) XS-2	0 - 100 ppm	1 ppm	6810370
Oxygen (O ₂) XS-2	0 - 0.25 Vol.	0.10% Vol.	6810375
XS-μPac DrägerSensor®			
Description	Measuring Range	Resolution	Part No. Replace.
Carbon Monoxide (CO) XS-μPac	0 - 999 ppm	1 ppm	6810030
Hydrogen Sulfide (H ₂ S) XS-μPac	0 - 99 ppm	1 ppm	6810032
Oxygen (O ₂) XS-μPac	0 - 25% Vol.	0.1% Vol.	6810034

FIRE PROTECTION SERVICE INC.**FPS-HOUSTON****Ph: 713-924-9600****Fx: 713-923-6272****FPS-NEW ORLEANS****Ph: 504-466-8003****Fx: 504-469-9922****FPS-CORPUS CHRISTI****Ph: 361-289-9102****Fx: 361-289-1421****FPS-USA**

Serving the marine and offshore industries since 1952

sales@fps-usa.com • www.fps-usa.com