



MEASURING INSTRUMENTS

Clamp-meters



Cat.No.	Description
662140	Digital clamp-meter 200/600A AC, 200/600VAC, 2kOhm, 2kHz/5 MHz, with case
662152	Digital clamp-meter 40/400/1000A AC, 400/750VAC, 4kOhm, 4kHz/4MHz with continuity tester and case
662153	Digital clamp-meter 400/1200A AC/DC, 750V AC/DC, 200Ohm, data-hold en peakhold function with continuity tester and case

Multimeters



1

Cat.No.	Description	Fig.
662214	Analogue multimeter 600V AC/DC, 300mA DC, 300KOhm, continuity test	1
662222	Small digital multimeter 0/250V AC/DC, 0/10A DC, 0/200MOhm with diode and continuity tester	
662226	Digital multimeter 0/600V AC/DC, 0/10A AC/DC, 0/200MOhm, 0/20mFd	2
662228	Digital multimeter UT193C , true RMS meter, 600V AC/DC, 10A AC/DC 60MOhm	
662238	Digital multimeter Fluke 179 , 1000V AC/DC 10A AC/DC, 50MOhm with holster	
662240	Digital multimeter Fluke 77 , 1000 V AC/DC 10A AC/DC, 32MOhm with holster	3
662242	Digital multimeter Fluke 87-5 , true RMS meter 1000V AC/DC, 10A AC/DC, 40MOhm, 50nS, 5mFd, 200kHz with holster	



2



3

Infrared thermometer



Cat.No.	Description
662300	Digital infrared thermometer -50 to 900 degrees C. in case