



MEASURING INSTRUMENTS

Ammeters, moving iron, panel mounting 72x72 mm, scale 90°,
AC 25-100Hz, for direct connection (without current
transformer) with 2 times overload capacity



Cat.No.	Ampere	
665004	1	no overload capacity
665007	2.5	
665010	4	
665013	6	
665016	10	
665019	15	
665022	25	
665025	40	
665028	60	
665031	100	

Ammeters, moving iron, panel mounting 72x72 mm, scale 90°,
AC 25-100Hz, for use with current transformer /5A,
2 times overload capacity



Cat.No.	Ampere
665048	25
665051	50
665054	60
665057	100
665060	200
665063	400
665066	600
665069	1000

Current transformers secondary current 5A



Cat.No.	Ampere	VA
665086	25	5
665089	50	1.25
665092	60	1.25
665095	100	1.5
665098	200	10
665101	400	15
665104	600	15
665107	1000	15