

WIRING ACCESSORIES

Rotary switches, base mounting 440VAC (continuation)



Cat.No.	A.	Type	Pos.	Poles	Dim. x
382791	25	c/over	1-2-1-2	2	30
382795	40	c/over	1-2-1-2	2	70
382799	63	c/over	1-2-1-2	2	50
382803	16	c/over	1-2-1-2	3	42
382807	25	c/over	1-2-1-2	3	42
382811	40	c/over	1-2-1-2	3	90
382815	63	c/over	1-2-1-2	3	70
382819	16	c/over	1-2-1-2	4	54
382823	25	c/over	1-2-1-2	4	54
382827	40	c/over	1-2-1-2	4	110
382831	63	c/over	1-2-1-2	4	80

Rotary switches, panel mounting 440VAC



Cat.No.	A.	Type	Pos.	Poles	Dim. x
382951	16	on/off	0-1-0-1	1	12
382955	25	on/off	0-1-0-1	1	12
382959	40	on/off	0-1-0-1	1	20
382963	63	on/off	0-1-0-1	1	30
382967	16	on/off	0-1-0-1	2	18
382971	25	on/off	0-1-0-1	2	18
382975	40	on/off	0-1-0-1	2	30
382979	63	on/off	0-1-0-1	2	40
382983	16	on/off	0-1-0-1	3	24
382987	25	on/off	0-1-0-1	3	24
382991	40	on/off	0-1-0-1	3	40
382995	63	on/off	0-1-0-1	3	50
382999	16	on/off	0-1-0-1	4	30
383003	25	on/off	0-1-0-1	4	30
383007	40	on/off	0-1-0-1	4	50
383011	63	on/off	0-1-0-1	4	60
383015	16	c/over	0-1-0-2	1	18
383019	25	c/over	0-1-0-2	1	18
383023	40	c/over	0-1-0-2	1	30
383027	63	c/over	0-1-0-2	1	40
383031	16	c/over	0-1-0-2	2	30
383035	25	c/over	0-1-0-2	2	30
383039	40	c/over	0-1-0-2	2	60
383043	63	c/over	0-1-0-2	2	70
383047	16	c/over	0-1-0-2	3	42
383051	25	c/over	0-1-0-2	3	42
383055	40	c/over	0-1-0-2	3	80
383059	60	c/over	0-1-0-2	3	90
383063	16	c/over	0-1-0-2	4	54
383067	40	c/over	0-1-0-2	4	54